




L2 WINDING: START END GOES UP THROUGHBACK SIDE OF CORE  
 CONTINUE WINDING PASSING WIRE DOWN THROUGH HOLE FROM FRONT  
 SIDE OF CORE, WINDING IN COUNTER CLOCKWISE DIRECTION.  
 AFTER 29 TURNS, MAKE LOOP AND CONTINUE WINDING  
 5 MORE TURNS FOR FEEDBACK WINDING.

START OF PRIMARY WINDING  
 START OF FEEDBACK WINDING



LONG JUMPER BETWEEN POINTS "A" AND "A"